

## Mostradores metálicos de abrazaderas de tornillo



Descripción	
Referencia	Composición
<b>DEPANNE 244</b>	244 abrazaderas de tornillo : - 100 tipo mini PBM : 10 x PBM 8 / 10 x PBM 9 / 10 x PBM 10 / 10 x PBM 11 / 10 x PBM 12 / 10 x PBM 13 / 10 x PBM 14 / 10 x PBM 15 / 10 x PBM 16 / 10 x PBM 17 - 144 tipo estándar PBS : 12 x PBS9 814 / 12 x PBS9 1117 / 12 x PBS9 1320 / 24 x PBS9 1524 / 12 x PBS9 1928 / 12 x PBS9 2232 / 12 x PBS9 2638 / 12 x PBS9 3244 / 12 x PBS9 3850 / 12 x PBS9 4456 / 12 x PBS9 5065 - 1 destornillador flexible : PB 3000
<b>DEPANNE 400</b>	400 abrazaderas de tornillo : - 100 tipo mini PBM : 10 x PBM 8 / 10 x PBM 9 / 10 x PBM 10 / 10 x PBM 11 / 10 x PBM 12 / 10 x PBM 13 / 10 x PBM 14 / 10 x PBM 15 / 10 x PBM 16 / 10 x PBM 17 - 300 tipo estándar PBS : 25 x PBS9 814 / 25 x PBS9 1117 / 25 x PBS9 1320 / 50 x PBS9 1524 / 25 x PBS9 1928 / 25 x PBS9 2232 / 25 x PBS9 2638 / 25 x PBS9 3244 / 25 x PBS9 3850 / 25 x PBS9 4456 / 25 x PBS9 5065 - 1 destornillador flexible : PB 3000

